



Fig. 5-5: Machine frame mounting, dimensioned drawing

- 1 Hexagon bolt with lock washer
- 2 Locating pin
- 3 Mounting surface, machined

5.4 Connecting cables and interfaces

Connecting cables

The connecting cables comprise all the cables for transferring energy and signals between the robot and the robot controller. They are connected to the robot combo box with connectors.

The following diagram provides an overview of the available connecting cables. (>>> [Fig. 5-6](#))